

Downloading, Installing and Setting up Koamtac KT Synch Software

# Downloading

- Go to the following url:
- <u>https://koamtac.com/support/downloads/applications/</u>



- Select v2.24 (outdated)
- The file will download to your downloads folder:



#### Installation

- If you have not already opened the Downloads folder, go to it now.
- Right click on the file KTSync\_Driver\_installer\_v224.zip and select 'extract all'.
- A 'Select Destination and Extract Files' message will appear. Just click on the 'extract' button.
- You will see a folder called 'KTSync\_Driver\_Installer\_V224'. Double click to view contents.
- Double click on setup.exe and follow the prompts and the following message will be displayed:

Application an	d driver has been installed succ	accfullu
Application an	a anver has been installed suct	Jossiany
	OK	

• The following icon should now be on your desktop:



## Configuration

- Double click on the KTSync.exe icon to open the program.
- Click on settings.
- Destination of Data:
  - Select 'File' and click on the 'New' button. Navigate to your Desktop and create a new folder called KDC and select that as the destination:



- Synchronisation Methods
  - Fast Synchronisation in Burst Mode
  - Synchronize Normal Data (maybe greyed out and ticked)
  - Synchronize Application Data (maybe greyed out and ticked)
  - o Remainder un ticked
- Current KDC Wedge Method
  - No change
- Synchronisation Options
  - Synchronize KDC Date/Time with PC Date/Time
  - Remainder unticked
- Application Options
  - No Change
- To save changes click on OK:

Synchronization Settings	- X	
Destination of Data	Synchronization Options	
File	Synchronize KDC Date/Time with PC Date/Time	
C:\Users\marti\OneDrive\Desktop\New	Delays between Barcodes 100 📩 msecs	
C Active Window	Delays between fields	
C Microsoft Excel	Delays between Characters 1msecs	
C Select from Currently Running Application scannerHire220627.docx ⋅ Word	Synchronization start delay 2 - secs	
Synchronization Methods	🗆 Attach Timestamp 🛛 Attach Barcode Type	
Fast Synchronization in Burst Mode	Attach Serial Number End Of Record	
Synchronize Normal Data	Prefix	
Synchronize Application Data		
Clear KDC Memory after Synchronization	1234 Suffix	
Automatically Synchronize after Connection	Data Order <data><timestamp><type> 💌</type></timestamp></data>	
Beep while Synchronization	Data Delimiter Tab	
Append data to file	Record Delimiter CR(\r) & LF(\n)	
Current KDC Wedge Method	Application Options	
Enable Wedge(Handheld Scanner Mode)	🗖 Synchronize Non-compliant Data	
✓ Keep Scanned Data in KDC	🗖 Consolidate Steps In One Record	
Keep Scanned Data in KDC if Sent	Attach Quantity End Of Field	
Keep Scanned Data in KDC if not Sent	🗖 Attach Zero(0) Quantity	
	Attach Master/Slave and OK/NG Flag	
ОК	Cancel	

### Basic Usage

## To synchronise to your designated folder

- Connect your KDC Scanner to a USB port. Once connected, the app should say 'Connected to COMx' where x is a number
- Click on the Synchronize Button



#### To delete data

- Instructions for transferring data to BatchLine are contained in the stock take instructions. Once the data has been transferred it is necessary to delete the contents of the gun in order to avoid duplication.
- Click on the KDC Menu button
- Then click on System Config
- Then click on Clear Memory
- Click on Save to exit

Download the Stocktake instructions from the Batch website: www.batch.co.uk